

Church Street Force Main Repair Presentation



Presented March 21, 2016

Director: Chris Jacobs P.E., LLS

Deputy Director: Jennifer Hale P.E., CPESC

Failure location

WWTP




View toward Rt. 101



View from Rt. 101





Hampton Force Main Repair
First Day Mat Install – 3-15-16

Installation of Mats





Hampton Force Main Repair
Second Day Mat Install and
First Bridge Placement
– 3-16-16





Hampton Force Main Repair
Third Day Mat Install and Second
Bridge Placement – 3-17-16





Hampton Force Main Repair
Third Day Mat Install and
Second Bridge Placement
(Continued) – 3-17-16





Hampton Force Main Repair
Investigation and Repair Day
– 3-18-16






Hampton Force Main Repair
Investigation and Repair Day
– 3-18-16





Hampton Force Main Repair
Investigation and Repair Day
– 3-18-16





Hampton Force Main Repair
Investigation and Repair Day
(Continued) – 3-18-16





Hampton Force Main Repair
Investigation and Repair Day
(Continued) – 3-18-16





Hampton Force Main Repair
Investigation and Repair Day
(Continued) – 3-18-16





Hampton Force Main Repair
Investigation and Repair Day
(Continued) – 3-18-16





Hampton Force Main Repair
Investigation and Repair Day
(Continued) – 3-18-16






Hampton Force Main Repair
Investigation and Repair Day
(Continued) – 3-18-16





Hampton Force Main Repair
Investigation and Repair Day
– 3-18-16





Hampton Force Main Repair
Investigation and Repair Day
– 3-18-16





Mark B. along with the entire Severino Trucking Co. & Mabey Co. team- We Thank You!





Remove the pipe from the Marsh!

